

General Information

Date & Time: 22, May, 2026 15:36

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	2,906
Registration No.	NKU5810	Chassis No.	PAHACACA1S6424203
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	104	112	105
2	Boot Lid	75.9	74	66	89
3	Roof	131.2	167	107	118/133
4	Left Front Fender	106.0	112	106	100
5	Left Front Door	109.0	109	107	111
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	65.0	58	75	62
9	Right Front Fender	103.6	108	100	103
10	Right Front Door	101.7	99	104	102
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	76.8	82	87	62

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large	Remarks Roof - Repair Traces - Yes / (R) Side Gate - Scratch - Medium / Cargo Bed Floor - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Guard Frame - Scratch - Small / Cab Back Panel - Scratch - Medium / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet/ no tools and jack/ no spare tire/ 1 key/ no LTO plate