

General Information

Date & Time: 25, May, 2026 17:48

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	32,581
Registration No.	CCQ3095	Chassis No.	PAHACACA8S6422867
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.3	107	100	103
2	Boot Lid	56.1	47	53	69
3	Roof	115.0	126	117	109/108
4	Left Front Fender	110.0	113	107	110
5	Left Front Door	105.0	106	108	101
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	61.6	52	79	54
9	Right Front Fender	102.7	110	102	96
10	Right Front Door	103.6	100	103	108
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	67.4	63	66	73

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Side Gate - Scratch - Large / Rear Gate - Scratch - Large / Cargo Bed Floor - Scratch - Large / (L) Side Gate - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Dent - Small / (R) Front Door, Molding - Scratch - Medium / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
incomplete tools/ no jack and warranty booklet/ with spare tire and LTO plate/ 1 key