

## General Information

Date & Time: 25, May, 2026 12:21

|                  |           |                   |                   |
|------------------|-----------|-------------------|-------------------|
| Make             | Toyota    | Model             | Avanza            |
| YOM              | 2019      | Odo Meter Reading | 94,670            |
| Registration No. | NEN2421-1 | Chassis No.       | MHKM5EF2FKK019555 |
| CC               | 1.3       | Transmission      | A/T               |
| Fuel Type        | Gas       | Type of Body      | Wagon             |
| Colour           | Gray      |                   |                   |

## Body / Panel Condition



| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 114.3         | 113    | 126    | 104      |
| 2  | Boot Lid           | 95.6          | 96     | 95     | 96       |
| 3  | Roof               | 107.4         | 96     | 103    | 112/119  |
| 4  | Left Front Fender  | 104.6         | 95     | 111    | 108      |
| 5  | Left Front Door    | 105.9         | 124    | 100    | 94       |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 110.0         | 105    | 119    | 106      |
| 8  | Left Back Panel    | 95.5          | 91     | 100    | 96       |
| 9  | Right Front Fender | 184.3         | 194    | 185    | 174      |
| 10 | Right Front Door   | 99.3          | 100    | 98     | 100      |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 101.1         | 100    | 101    | 103      |
| 13 | Right Back Panel   | 85.9          | 95     | 86     | 78       |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : <b>C</b>                                                                                                                                                                                                                                                                 | Exterior Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>                                                                                                                                | <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| <p><b>Remarks</b><br/>Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Large / (R) Front Trim - Grime - Large / Rear Seat - Grime - Small / Overall Interior - Smell - Yes</p> | <p><b>Remarks</b><br/>(R) Front Fender - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Center Panel - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch, Peeled - Yes / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Crack, Gap - Large / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Dent - Small</p> |
| Frame Evaluation : <b>A</b>                                                                                                                                                                                                                                                                    | Functional Evaluation : <b>C</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| <p><b>Remarks</b><br/>Defects not found</p>                                                                                                                                                                                                                                                    | <p><b>Remarks</b><br/>Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |

| Inspector Notes                                                                                                                                                                                                        |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| With LTO plate, with warranty booklet, incomplete tools, with jack, with seat cover except driver seat, with spare tire, no spare key, air-condition weak, with hairline scratches, with foul smell, possible flooded. |