

General Information

Date & Time: 02, Jun, 2026 11:01

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	1
Registration No.	GAV2552	Chassis No.	MHKA4DE5FMJ016331
CC	1.0	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	E	Exterior Evaluation :	N / A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain			
Remarks (L) Front Trim - Grime - Small / Steering Wheel - Worn, Peel, Crack - Large / Ceiling - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Rear Trim - Grime - Medium / Rear Seat - Grime - Large / Mat Other - Grime - Large / (R) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Large / (R) Front Floor Mat - Grime - Large / Glove Box - Loose, Deformed - Small / (R) Front Seat - Grime - Large / (R) Front Seat belt - Grime - Large / Overall Interior - Animal Hair - Yes / Overall Interior - Smell - Yes / (L) Front Seat belt - Grime - Large		Remarks Defects not found	
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

Possible flooded. Towed unit. None moving unit. Scratches at the exterior. Mileage cannot determined. Functions cannot determined. Shifter knobs missing. Steering trim detached. Without spare tire, tools, Rear LTO plate. With warranty booklet, seatcover and 2keys.