

General Information

Date & Time: 29, May, 2026 16:13

Make	Chevrolet	Model	Trailblazer
YOM	2015	Odo Meter Reading	91,143
Registration No.	GEB4862	Chassis No.	MMM156MK0FH628203
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	133.0	126	139	134
2	Boot Lid	158.0	170	149	155
3	Roof	124.7	133	115	130/121
4	Left Front Fender	260.6	252	261	269
5	Left Front Door	271.3	286	266	262
6	Center Panel Left				
7	Left Rear Door	138.3	138	139	138
8	Left Back Panel	147.3	144	147	151
9	Right Front Fender	230.6	239	203	250
10	Right Front Door	133.3	132	132	136
11	Center Panel Right				
12	Right Rear Door	129.0	127	129	131
13	Right Back Panel	342.3	177	605	245

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small / (R) Front Seat - Grime - Medium / (R) Rear Trim - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Seat belt - Grime - Small / (L) Front Seat - Grime - Minimal / (L) Front Seat belt - Grime - Small	Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Large / Overall Exterior - Worn as per age - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (R) Front Fender, Molding - Scratch - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / Overall Exterior - Re-Paint Uneven - Yes
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

Possible flooded. Visible hairline scratches. Repainted at exterior. Maintenance warning lamp on. Left side headlight busted. Right side down signal light busted. Rear gate trunk cannot open. Without warranty booklet, tools, jack. With sparetire, seatcover, LTO plate and 1key.