

General Information

Date & Time: 25, Jun, 2026 07:42

Make	Nissan	Model	NV350
YOM	2020	Odo Meter Reading	75,034
Registration No.	NFW7860	Chassis No.	JN1TC2EZ6Z0059671
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	133.6	148	112	141
2	Boot Lid	143.6	158	128	145
3	Roof	111.4	96	99	83/168
4	Left Front Fender				
5	Left Front Door	145.3	147	138	151
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	148.6	160	134	152
9	Right Front Fender				
10	Right Front Door	139.6	126	133	160
11	Center Panel Right				
12	Right Rear Door	150.3	147	159	145
13	Right Back Panel	172.3	211	154	152

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Worn as per age - Yes / Overall Interior - Animal Hair - Yes / Mat Other - Missing - Yes / (R) Front Floor Mat - Cut, Crack - Large / Ceiling - Cut, Crack - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Center Panel - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / Front Panel - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Dent - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

turn signal issue/ air-conditioning issue/ plate light issue/ parking brake issue/ light scratches around the exterior/ possible flooding/ no jack and tools/ with Lto plate and warranty booklet/ with Spare tire