

General Information

Date & Time: 25, Feb, 2025 10:05

Make	Toyota	Model	Vios
YOM	2023	Mileage	15,570
Registration No.	DBJ6249	Chassis No.	PA1B18F32P4221189
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	127	108	116
2	Boot Lid	122.0	129	124	113
3	Roof	106.0	107	107	101/109
4	Left Front Fender	106.3	110	101	108
5	Left Front Door	108.6	113	107	106
6	Center Panel Left				
7	Left Rear Door	105.6	110	101	106
8	Left Back Panel	102.8	99	107	103
9	Right Front Fender	102.3	103	102	102
10	Right Front Door	106.3	108	101	110
11	Center Panel Right				
12	Right Rear Door	107.6	103	102	118
13	Right Back Panel	111.3	110	107	117

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
without LTO plate/No reverse camera/No spare tire/No jack and tools/No warranty booklet/trunk room without cover