

General Information

Date & Time: 15, Jun, 2026 07:53

Make	Mitsubishi	Model	Mirage
YOM	2023	Odo Meter Reading	61,764
Registration No.	NFB4959	Chassis No.	PAEA13TJPPA010677
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	113	113	109
2	Boot Lid	96.4	92	111	87
3	Roof	106.8	93	95	89/150
4	Left Front Fender	107.3	109	100	113
5	Left Front Door	131.0	135	131	127
6	Center Panel Left				
7	Left Rear Door	96.3	97	95	97
8	Left Back Panel	497.3	137	450	905
9	Right Front Fender	104.4	107	96	110
10	Right Front Door	97.7	96	97	100
11	Center Panel Right				
12	Right Rear Door	93.0	95	90	95
13	Right Back Panel	107.6	103	106	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	Exterior Evaluation : E A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Medium	Remarks (L) Rear Fender - Repair Traces - Yes / (L) Front Fender, Molding - Crack, Gap - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/no warranty booklet/no tools and jack/with spare tire/no spare key/no reverse camera/hairline scratches on the body/center console issue/scratches on headlight cover/abnormal engine noise