

General Information

Date & Time: 25, Feb, 2025 18:05

Make	Suzuki	Model	Carry
YOM	2023	Mileage	14,436
Registration No.	NHF4432	Chassis No.	MHYDC61T7PJ213838
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	124	105	121
2	Boot Lid	333.4	712	89	199
3	Roof	96.4	108	106	87/85
4	Left Front Fender	129.3	124	136	128
5	Left Front Door	104.5	111	106	97
6	Center Panel Left	107.6	112	106	105
7	Left Rear Door				
8	Left Back Panel	407.6	505	107	611
9	Right Front Fender	91.3	96	90	88
10	Right Front Door	85.8	83	87	88
11	Center Panel Right	102.7	103	107	98
12	Right Rear Door				
13	Right Back Panel	463.5	673	98	620

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Door - Repair Traces - Yes / Front Panel - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / (L) Side Gate - Repair mark - Yes / (R) Side Gate - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Gate - Scratch - Small / (R) Side Gate - Scratch - Large / Cargo Bed Floor - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no warranty booklet/ incomplete tools/ no jack/ with spare tire/ with LTO plate