

General Information

Date & Time: 25, Feb, 2025 14:39

Make	Suzuki	Model	APV
YOM	2022	Mileage	54,639
Registration No.	NHB2539	Chassis No.	MHYDN71V5PJ401078
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.9	102	100	104
2	Boot Lid	105.3	102	116	98
3	Roof	90.5	83	78	92/108
4	Left Front Fender	78.9	70	78	89
5	Left Front Door	91.2	92	90	92
6	Center Panel Left				
7	Left Rear Door	96.6	98	100	93
8	Left Back Panel	99.2	103	97	97
9	Right Front Fender	102.0	108	102	96
10	Right Front Door	101.1	108	97	99
11	Center Panel Right				
12	Right Rear Door	106.3	104	106	109
13	Right Back Panel	109.6	109	106	114

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Worn, Scratch, Cut, Crack - Medium / Overall Interior - Smell - Yes / (R) Front Trim - Worked - Large / (L) Front Trim - Worked - Large	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Dent - Small / (L) Rear Fender, Molding - Dent - Small / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet/ with spare tire and jack/ abnormal noise on steering wheel/ dirty interior/ with LTO plate/ incomplete tools