


General Information

Date & Time: 25, Feb, 2025 18:40

Make	Suzuki	Model	APV
YOM	2023	Mileage	8,063
Registration No.	NHH2281	Chassis No.	MHYDN71V5RJ4010221
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	110	113	110
2	Boot Lid	105.5	106	113	98
3	Roof	93.6	82	78	112/103
4	Left Front Fender	90.8	79	95	98
5	Left Front Door	110.0	111	107	112
6	Center Panel Left				
7	Left Rear Door	113.3	114	117	109
8	Left Back Panel	103.6	101	101	109
9	Right Front Fender	101.0	104	106	93
10	Right Front Door	112.6	125	107	106
11	Center Panel Right				
12	Right Rear Door	120.6	118	120	124
13	Right Back Panel	106.0	108	106	104

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Dent - Small / (R) Step, In-panel, Side Spoiler - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
no warranty booklet/ no tools/ with spare tire and jack/ no LTO plate