

General Information

Date & Time: 25, Feb, 2025 16:36

Make	Lexus	Model	ES
YOM	2012	Mileage	179,275
Registration No.	MLB575	Chassis No.	JTHBK1GG602010062
CC	3.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	189.0	165	216	186
2	Boot Lid	182.6	208	159	181
3	Roof	128.0	123	133	133/123
4	Left Front Fender	191.6	208	196	171
5	Left Front Door	117.6	117	119	117
6	Center Panel Left				
7	Left Rear Door	119.6	126	118	115
8	Left Back Panel	128.3	132	120	133
9	Right Front Fender	126.6	142	125	113
10	Right Front Door	159.6	164	154	161
11	Center Panel Right				
12	Right Rear Door	112.6	111	113	114
13	Right Back Panel	119.0	117	111	129

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Worn - Yes / Overall Interior - Worn as per age - Yes / (R) Rear Trim - Worked - Small / Rear Seat - Worn - Yes	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes

Inspector Notes
with warranty booklet/ with spare tire and tools/ with jack/ with LTO plate/ had lights flickering/