

General Information

Date & Time: 25, Jun, 2026 16:47

Make	Toyota	Model	Lite Ace
YOM	2025	Odo Meter Reading	28,047
Registration No.	FAQ9368	Chassis No.	MHKU3FE10RK008841
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	62.6	78	55	55
2	Boot Lid	68.5	76	59	71
3	Roof	54.6	43	52	77/47
4	Left Front Fender	49.6	45	47	57
5	Left Front Door	53.1	54	55	50
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	64.1	53	84	56
9	Right Front Fender	53.0	56	52	51
10	Right Front Door	48.5	48	52	47
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	106.3	115	115	89

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Large	Remarks (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Side Gate - Repair mark - Yes / Rear Gate - Repair mark - Yes / Rear Gate - Scratch & Dent - Medium / (L) Side Gate - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Cargo Bed Floor - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with lto plate, with warranty booklet, with spare tire, with jack, with. tools, loosed rear step pad