

General Information

Date & Time: 26, Jun, 2026 15:57

Make	Suzuki	Model	Swift
YOM	2020	Odo Meter Reading	37,853
Registration No.	YAA7895	Chassis No.	MMSZC63S1LR100102
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	221.3	288	195	181
2	Boot Lid	111.1	115	119	99
3	Roof	114.7	107	104	129/119
4	Left Front Fender	170.3	158	154	199
5	Left Front Door	154.6	172	148	144
6	Center Panel Left				
7	Left Rear Door	172.3	180	186	151
8	Left Back Panel	189.6	195	206	168
9	Right Front Fender	161.3	180	152	152
10	Right Front Door	138.6	112	136	168
11	Center Panel Right				
12	Right Rear Door	151.3	171	144	139
13	Right Back Panel	197.3	201	210	181

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / Rear Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Minimal / Carpet - Worked - Minimal / (L) Front Seat - Cut, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Steering Wheel - Worn, Peel, Crack - Small	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Antennae - Damaged - Yes / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small / (R) Mirror - Stuck - Yes
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare, 1key, no warranty booklet and tools and Jack, scratches on headlights and taillights, aircon issue