

General Information

Date & Time: 26, Jun, 2026 16:02

Make	Mitsubishi	Model	Strada
YOM	2017	Odo Meter Reading	105,804
Registration No.	DAF1355	Chassis No.	MMBJYKK10HH014547
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	235.0	207	256	242
2	Boot Lid	474.6	256	879	289
3	Roof	101.6	94	78	117/118
4	Left Front Fender	106.3	102	105	112
5	Left Front Door	208.0	162	224	238
6	Center Panel Left				
7	Left Rear Door	98.2	99	95	101
8	Left Back Panel	114.3	132	94	117
9	Right Front Fender	304.0	223	242	447
10	Right Front Door	387.3	353	589	220
11	Center Panel Right				
12	Right Rear Door	447.6	246	204	893
13	Right Back Panel	522.0	1,147	253	166

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / Overall Interior - Worn as per age - Yes	Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Dent - Small / (L) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Rear Gate - Scratch & Dent - Small / (R) Side Gate - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Dent - Medium / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

horn issue/ side mirror issue/ air-conditioning issue/ possible flooding/ no jack and tools/ light scratches around the exterior/no warranty booklet/ with spare tire and LTO plate/