

General Information

Date & Time: 06, Jul, 2026 17:37

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	46,708
Registration No.	NIM9678	Chassis No.	PA1B18F32P4211892
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.6	146	110	133
2	Boot Lid	143.0	123	178	128
3	Roof	122.5	123	124	116/127
4	Left Front Fender	102.6	102	104	102
5	Left Front Door	106.3	107	116	96
6	Center Panel Left				
7	Left Rear Door	158.6	165	150	161
8	Left Back Panel	181.3	210	170	164
9	Right Front Fender	103.6	105	104	102
10	Right Front Door	140.3	148	135	138
11	Center Panel Right				
12	Right Rear Door	175.6	171	168	188
13	Right Back Panel	111.6	110	110	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Small / Rear Seat - Grime - Large / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Small	Remarks (L) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Crack, Gap - Medium / (R) Front Door, Molding - Scratch - Medium / Overall Exterior - Full Re-Paint in same color - Yes / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With LTO plate, no warranty booklet, incomplete tools, with jack, no spare key, no spare tire, no seat cover, no reverse camera, blurred instrument panel glass, repainted, with hairline scratches, modified/replaced wheels.