

General Information

Date & Time: 26, Feb, 2025 12:24

Make	Suzuki	Model	APV
YOM	2024	Mileage	5,688
Registration No.	NKD7541	Chassis No.	MHYDN71V7RJ402025
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	116	120	105
2	Boot Lid	103.4	95	116	99
3	Roof	93.9	89	88	105/94
4	Left Front Fender	93.0	83	90	106
5	Left Front Door	110.3	110	109	112
6	Center Panel Left				
7	Left Rear Door	113.6	109	114	118
8	Left Back Panel	109.3	117	108	103
9	Right Front Fender	98.6	104	102	90
10	Right Front Door	107.7	117	107	99
11	Center Panel Right				
12	Right Rear Door	109.0	106	106	115
13	Right Back Panel	110.6	102	113	117

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Overall Interior - Smell - Yes / Dashboard - Worn, Scratch, Cut, Crack - Medium	Remarks (R) Front Door, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Dent - Small / (R) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet/ with spare tire / no tools / no jack/ no LTO plate