

General Information

Date & Time: 26, Feb, 2025 15:02

Make	Toyota	Model	Vios
YOM	2024	Mileage	1,125
Registration No.	BAG4180	Chassis No.	PA1B18F34R4259932
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	110	106	116
2	Boot Lid	109.6	109	108	112
3	Roof	105.0	101	102	100/117
4	Left Front Fender	100.8	99	99	105
5	Left Front Door	99.5	100	103	96
6	Center Panel Left				
7	Left Rear Door	102.0	106	103	97
8	Left Back Panel	112.0	118	107	111
9	Right Front Fender	102.5	103	99	106
10	Right Front Door	101.9	101	109	96
11	Center Panel Right				
12	Right Rear Door	109.0	111	108	108
13	Right Back Panel	105.0	106	101	108

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with spare tire, jack and tools. without warranty booklet. NO LTO plate. adhesive marks at rear windshield and roof