

General Information

Date & Time: 13, Jul, 2026 16:23

Make	Toyota	Model	Avanza
YOM	2024	Odo Meter Reading	1
Registration No.	GBA5265	Chassis No.	MHFAA1BYXP0017588
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	White		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :		E	Exterior Evaluation :		N / A	
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain						
Remarks Ceiling - Grime - Large / (R) Front Seat - Grime - Large / (R) Front Floor Mat - Grime - Large / (L) Front Floor Mat - Grime - Large / Mat Other - Grime - Large / (L) Front Seat - Grime - Large / (R) Rear Trim - Grime - Large / (R) Front Trim - Grime - Large / Rear Seat - Grime - Large / (L) Front Trim - Grime - Large / (L) Rear Trim - Grime - Large / Overall Interior - Animal Hair - Yes / Overall Interior - Smell - Yes			Remarks Defects not found			
Frame Evaluation :			N / A	Functional Evaluation :		N / A
Remarks Defects not found			Remarks Defects not found			

Inspector Notes
Flooded unit. Mileage cannot be determined. Functions cannot be determined. Rear gate window totally broken. Large gap and dent at right side rear bumper up to front side. Large dent at front. Large dent and scratch at bonnet. Front windshield totally crack. Large dent and scratches at exterior. Without warranty booklet, tools. With sparetire, jack, seatcover, LTO plate and 1key.