

General Information

Date & Time: 20, Jul, 2026 15:50

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	20,073
Registration No.	DCE2943	Chassis No.	PAHACACA4S6432232
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	MPV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	100	105	108
2	Boot Lid	103.9	109	97	106
3	Roof	118.0	130	120	113/109
4	Left Front Fender	102.4	111	118	78
5	Left Front Door	114.3	113	116	114
6	Center Panel Left	116.6	116	112	122
7	Left Rear Door				
8	Left Back Panel	98.5	101	98	96
9	Right Front Fender	105.3	105	108	103
10	Right Front Door	116.0	110	103	135
11	Center Panel Right	111.3	113	115	106
12	Right Rear Door				
13	Right Back Panel	108.3	105	118	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	D
The diagram shows the interior of a vehicle from a top-down perspective. Inspection points are labeled as follows: 1: Front floor mat area. 2: Driver's side front seat. 3: Center console between front seats. 4: Passenger's side front seat. 5: Rear bench seat. 6: Left side door panel. 7: Right side door panel. 8: Rear floor area. 9: Headrest of driver's seat. 10: Headrest of passenger's seat.		The diagram shows the exterior of a vehicle from a top-down perspective. Inspection points are labeled as follows: 1: Front hood/bonnet. 2: Front left headlight. 3: Front right headlight. 4: Front bumper. 5: Front grille. 6: Front left fender. 7: Front right fender. 8: Front left wheel/tire. 9: Front right wheel/tire. 10: Front left door. 11: Front right door. 12: Front left mirror. 13: Front right mirror. 14: Front windshield. 15: Roof. 16: Rear window. 17: Rear bumper. 18: Rear left wheel/tire. 19: Rear right wheel/tire.	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Dashboard - Worked - Minimal / Rear Seat - Grime - Small / Ceiling - Grime - Small		Remarks Roof - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Side Gate - Scratch & Dent - Small / (R) Guard Frame - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Guard Frame - Scratch - Small / (L) Side Gate - Scratch & Dent - Minimal / Cab Back Panel - Scratch - Small / Cargo Bed Floor - Scratch - Medium / Rear Gate - Modified - Medium / Rear Gate - Dent - Minimal	
Frame Evaluation :	A	Functional Evaluation :	A
Remarks Defects not found		Remarks Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate, with spare tire, with jack, with manual and warranty booklet, no tools, no spare key, no reverse camera, reverse light issue, scratches and dent on exterior, scratches in taillight and headlight lens.