

General Information

Date & Time: 04, Mar, 2025 10:59

Make	Toyota	Model	Vios
YOM	2021	Mileage	90,887
Registration No.	EAF7977	Chassis No.	PA1B18F36L4132249
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.7	100	92	101
2	Boot Lid	96.8	96	95	100
3	Roof	92.2	102	88	86/93
4	Left Front Fender	85.7	87	84	87
5	Left Front Door	89.0	92	92	83
6	Center Panel Left				
7	Left Rear Door	93.8	101	91	90
8	Left Back Panel	100.9	105	98	99
9	Right Front Fender	85.8	81	88	89
10	Right Front Door	92.5	82	90	106
11	Center Panel Right				
12	Right Rear Door	96.5	99	91	100
13	Right Back Panel	99.3	100	98	101

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : E	Exterior Evaluation : D
The diagram shows the interior of a vehicle from a top-down perspective. The front seats are pink and labeled with 'Y4' and '9'. The rear seat is also pink and labeled with '7' and 'Y4'. The center console is labeled '3'. The dashboard area is labeled '1'. Various other points are labeled with letters like 'A4', 'D', 'A2', 'Y3', 'T', 'L', 'Y2', '6', 'S', and '10'.	The diagram shows three views of a vehicle's exterior: front, left side, and right side. The front view is labeled with '11', 'U2', '12', '13', '14', 'AU2', and 'U2'. The left side view is labeled with 'A2', '7', '10', 'SC3', '8', 'A2', and '9'. The right side view is labeled with 'A2', 'AU4', 'A2', '3', 'AU3', and '4'.
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / Mat Other - Grime - Medium / (R) Front Floor Mat - Grime - Large / (R) Front Seat - Grime - Medium / (R) Front Trim - Worked - Small / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Large / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Worked - Large / (L) Front Trim - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Large / (L) Front Seat - Grime - Large / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (R) Front Seat - Cigarette Burns - Burnt, Hole / Carpet - Worn, Scratch, Cut, Crack - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Rust, Corrosion - Medium / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Condition of Welding ? - Yes	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet, with jack and incomplete tools, with spare tire, with LTO plate, steering wheel control button issue