

General Information

Date & Time: 17, Jul, 2026 16:12

Make	Suzuki	Model	Carry
YOM	2024	Odo Meter Reading	49,544
Registration No.	NFS2612	Chassis No.	MHYDC61T8RJ211406
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.0	126	109	107
2	Boot Lid	122.3	111	126	130
3	Roof	103.4	108	112	94/100
4	Left Front Fender	111.0	105	125	103
5	Left Front Door	105.0	103	110	102
6	Center Panel Left	101.0	108	108	87
7	Left Rear Door				
8	Left Back Panel	149.6	108	184	157
9	Right Front Fender	127.0	118	125	138
10	Right Front Door	110.3	112	114	105
11	Center Panel Right	105.2	116	102	98
12	Right Rear Door				
13	Right Back Panel	135.6	136	124	147

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Large / Glove Box - Worn, Scratch, Cut, Crack - Minimal / Trim Other - Cut, Crack - Small / Rear Seat - Cut, Crack - Small / (L) Front Seat - Cut, Crack - Minimal / (L) Front Trim - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Small / Overall Interior - Worn as per age - Yes	Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Minimal / Roof - Scratch - Medium / (R) Side Gate - Scratch & Dent - Large / Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Center Panel - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Side Gate - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Front Panel - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with spare tire and warranty booklet, 1key, no jack and tools, scratches on headlights and taillights,,rear window lock issue