

General Information

Date & Time: 17, Jul, 2026 16:15

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	9,128
Registration No.	NEZ9747	Chassis No.	PAHACACA8S6430659
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	111	115	107
2	Boot Lid	43.8	44	46	41
3	Roof	127.0	141	129	120/118
4	Left Front Fender	118.0	117	111	126
5	Left Front Door	116.6	112	119	119
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	55.9	61	59	48
9	Right Front Fender	107.3	108	110	104
10	Right Front Door	95.4	106	111	69
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	61.1	64	53	66

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Guard Frame - Scratch & Dent - Large / Cargo Bed Floor - Scratch & Dent - Large / Rear Gate - Scratch - Medium / (L) Side Gate - Crack, Gap - Large / Roof - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

no warranty booklet/ light scratches around the exterior/ with jack and spare tire/ with LTO plate and tools/ no warranty booklet