

General Information

Date & Time: 20, Jul, 2026 15:19

Make	Toyota	Model	Hilux Tamaraw
YOM	2026	Odo Meter Reading	14,501
Registration No.	DCE3936	Chassis No.	PAHACACA3S6431685
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	105	113	105
2	Boot Lid	52.3	58	49	51
3	Roof	108.0	141	128	115/48
4	Left Front Fender	111.6	111	110	114
5	Left Front Door	116.3	116	114	119
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	50.2	54	45	52
9	Right Front Fender	104.0	105	104	103
10	Right Front Door	89.1	105	109	54
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	49.5	52	49	48

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Guard Frame - Scratch & Dent - Large / Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Cargo Bed Floor - Scratch & Dent - Large / (L) Guard Frame - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

no jack and tools/ light scratches around the exterior / with LTO plate and warranty booklet/ with spare tire/