

General Information

Date & Time: 22, Jul, 2026 07:39

Make	Suzuki	Model	Ertiga
YOM	2024	Odo Meter Reading	35
Registration No.	DNV3612	Chassis No.	MHYNC32S1RJ105114
CC	1.5	Transmission	M/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.4	98	85	115
2	Boot Lid	100.0	100	94	107
3	Roof	99.6	90	97	106/105
4	Left Front Fender	66.8	102	92	7
5	Left Front Door	111.3	113	107	114
6	Center Panel Left				
7	Left Rear Door	113.6	115	114	112
8	Left Back Panel	100.8	105	104	94
9	Right Front Fender	102.7	108	96	104
10	Right Front Door	121.0	125	112	126
11	Center Panel Right				
12	Right Rear Door	117.3	110	114	128
13	Right Back Panel	104.0	105	104	103

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / (L) Front Trim - Grime - Minimal	Remarks (L) Front Fender - Repair Traces - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Roof - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with LTO plate, with warranty and manual booklet, with jack and tools, with spare tire and key, minor scratches on exterior, minor scratches in taillight and headlight.