

General Information

Date & Time: 21, Jul, 2026 15:43

Make	Suzuki	Model	Ertiga
YOM	2024	Odo Meter Reading	47
Registration No.	DNV3610	Chassis No.	MHYNC32S8RJ100881
CC	1.5	Transmission	M/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.5	109	89	98
2	Boot Lid	93.7	91	99	92
3	Roof	89.0	93	83	92/89
4	Left Front Fender	89.1	91	85	92
5	Left Front Door	109.0	114	104	109
6	Center Panel Left				
7	Left Rear Door	109.0	113	107	107
8	Left Back Panel	91.9	95	98	82
9	Right Front Fender	77.0	81	75	76
10	Right Front Door	98.4	100	97	98
11	Center Panel Right				
12	Right Rear Door	97.0	95	91	105
13	Right Back Panel	85.5	79	86	92

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate/with warranty booklet/with tools and jack/with spare tire/with spare key/no reverse camera