

General Information

Date & Time: 03, Mar, 2025 17:29

Make	Toyota	Model	Wigo
YOM	2021	Mileage	59,225
Registration No.	NDZ5393	Chassis No.	MHKA4DF5FMJ054787
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.4	100	101	82
2	Boot Lid	93.7	91	99	91
3	Roof	82.1	73	86	90/79
4	Left Front Fender	94.1	94	95	93
5	Left Front Door	89.7	93	88	89
6	Center Panel Left				
7	Left Rear Door	89.3	90	91	87
8	Left Back Panel	87.2	88	90	83
9	Right Front Fender	89.9	91	90	89
10	Right Front Door	88.4	88	88	90
11	Center Panel Right				
12	Right Rear Door	85.4	85	87	84
13	Right Back Panel	81.4	84	80	81

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Medium	Remarks (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (L) Center Panel - Scratch - Small / (L) Front Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
trunk floor missing. without warranty booklet, jack and tools. with spare tire and LTO plate.