

General Information

Date & Time: 04, Mar, 2025 12:26

Make	Toyota	Model	Vios
YOM	2024	Mileage	29,572
Registration No.	DBF6556	Chassis No.	PA1B18F39R4248375
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	117	106	116
2	Boot Lid	100.2	97	99	104
3	Roof	108.5	111	111	102/110
4	Left Front Fender	97.3	99	95	98
5	Left Front Door	100.1	101	100	99
6	Center Panel Left				
7	Left Rear Door	111.6	114	113	108
8	Left Back Panel	107.3	102	109	111
9	Right Front Fender	104.3	103	105	105
10	Right Front Door	101.7	106	101	98
11	Center Panel Right				
12	Right Rear Door	114.3	106	111	126
13	Right Back Panel	112.3	111	112	114

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small / Rear Seat - Grime - Large	Remarks (R) Rear Door, Molding - Dent - Small / (L) Front Fender, Molding - Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Crack, Gap - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
crack left taillight. with warranty booklet. without spare tire, jack and tools. without LTO plate.