


General Information

Date & Time: 23, Apr, 2025 13:24

Make	Toyota	Model	Vios
YOM	2025	Mileage	14,810
Registration No.	DBP8279	Chassis No.	PA1B18F38R4262624
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	110	95	111
2	Boot Lid	99.8	94	102	103
3	Roof	89.2	95	99	82/82
4	Left Front Fender	89.1	87	90	91
5	Left Front Door	92.0	88	96	93
6	Center Panel Left				
7	Left Rear Door	99.7	116	91	92
8	Left Back Panel	97.7	106	95	92
9	Right Front Fender	91.7	92	87	97
10	Right Front Door	93.1	97	91	92
11	Center Panel Right				
12	Right Rear Door	95.3	96	91	99
13	Right Back Panel	97.7	89	94	110

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no LTO plate, with warranty booklet, no tools, with jack and spare tire, dome light issue, loosed left cheek light