

General Information

Date & Time: 23, Apr, 2025 17:05

Make	Toyota	Model	Vios
YOM	2024	Mileage	13,781
Registration No.	DBN7044	Chassis No.	PA1B18F3XP4233218
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.3	105	101	104
2	Boot Lid	102.0	99	105	102
3	Roof	97.9	108	98	93/92
4	Left Front Fender	96.2	93	94	102
5	Left Front Door	96.2	99	92	98
6	Center Panel Left				
7	Left Rear Door	108.4	127	102	96
8	Left Back Panel	104.0	113	103	96
9	Right Front Fender	100.9	107	100	96
10	Right Front Door	96.8	100	91	100
11	Center Panel Right				
12	Right Rear Door	99.3	95	98	105
13	Right Back Panel	99.9	94	94	112

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Small / Knobs - Worn, Peel, Crack - Small	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack and tools/No warranty booklet/reverse camera not working