


General Information

Date & Time: 10, Apr, 2025 13:12

Make	Toyota	Model	Vios
YOM	2024	Mileage	9,578
Registration No.	NHM4739	Chassis No.	PA1B18F39P4237986
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	111	104	111
2	Boot Lid	93.3	92	91	97
3	Roof	99.8	97	114	96/93
4	Left Front Fender	92.3	96	92	89
5	Left Front Door	93.7	96	90	95
6	Center Panel Left				
7	Left Rear Door	95.5	106	95	86
8	Left Back Panel	100.3	114	100	87
9	Right Front Fender	110.6	108	110	114
10	Right Front Door	82.7	95	77	76
11	Center Panel Right				
12	Right Rear Door	85.5	78	80	99
13	Right Back Panel	83.4	84	83	84

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Small / (L) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes	Remarks (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Roof - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, with jack, incomplete tools, with spare tire, with LTO plate, windshield washer issue