

General Information

Date & Time: 14, Apr, 2025 12:39

Make	Toyota	Model	Vios
YOM	2024	Mileage	14,338
Registration No.	CAZ9975	Chassis No.	PA1B18F37R4240226
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.3	119	109	106
2	Boot Lid	108.3	111	103	111
3	Roof	102.8	112	95	95/109
4	Left Front Fender	96.5	101	90	98
5	Left Front Door	98.7	100	98	98
6	Center Panel Left				
7	Left Rear Door	101.1	110	100	93
8	Left Back Panel	111.0	110	111	112
9	Right Front Fender	99.6	100	100	100
10	Right Front Door	83.6	82	84	84
11	Center Panel Right				
12	Right Rear Door	87.3	80	86	97
13	Right Back Panel	109.6	103	112	114

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet and LTO plate/ with spare tire and jack/ with tools