

General Information

Date & Time: 22, Apr, 2025 10:26

Make	Toyota	Model	Vios
YOM	2025	Mileage	5,584
Registration No.	NKK4300	Chassis No.	PA1B18F32R427445
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	108	100	104
2	Boot Lid	94.2	89	94	100
3	Roof	91.4	94	94	88/90
4	Left Front Fender	88.1	90	83	92
5	Left Front Door	94.8	93	94	98
6	Center Panel Left				
7	Left Rear Door	95.5	105	94	88
8	Left Back Panel	97.9	106	99	89
9	Right Front Fender	95.1	95	97	94
10	Right Front Door	88.2	93	82	89
11	Center Panel Right				
12	Right Rear Door	92.3	86	87	104
13	Right Back Panel	92.3	87	92	99

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Rear Fender, Molding - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with warranty booklet/with jack and tools