


General Information

Date & Time: 21, Apr, 2025 12:52

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,201
Registration No.	NKC6788	Chassis No.	PA1B18F34R4254892
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.3	112	93	99
2	Boot Lid	93.2	91	91	98
3	Roof	89.4	89	88	85/96
4	Left Front Fender	84.9	87	83	84
5	Left Front Door	88.6	86	94	87
6	Center Panel Left				
7	Left Rear Door	90.8	92	90	91
8	Left Back Panel	98.5	103	99	93
9	Right Front Fender	108.2	94	129	102
10	Right Front Door	93.5	94	93	94
11	Center Panel Right				
12	Right Rear Door	93.8	89	94	99
13	Right Back Panel	91.4	92	91	92

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large / Rear Seat - Grime - Minimal	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools/ with jack and spare tire/ with LTO plate/ power steering issue due to weak battery/ battery needs replacement/