

General Information

Date & Time: 05, Oct, 2024 10:24

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,073
Registration No.	DBP2133	Chassis No.	PA1B18F3XR4259269
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.4	110	94	106
2	Boot Lid	109.0	102	113	112
3	Roof	100.7	103	101	99/100
4	Left Front Fender	98.2	99	95	100
5	Left Front Door	100.9	101	98	104
6	Center Panel Left				
7	Left Rear Door	115.3	122	120	104
8	Left Back Panel	105.9	118	105	95
9	Right Front Fender	100.5	101	100	101
10	Right Front Door	97.0	94	100	97
11	Center Panel Right				
12	Right Rear Door	100.6	103	99	100
13	Right Back Panel	100.4	92	100	109

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A		Exterior Evaluation : B	
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Trunk Room - Loose, Deformed, Grime - Small / (R) Front Seat - Grime - Small / (L) Front Floor Lag - Cut, Crack - Small		Remarks (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

more light scratches around the exterior