

General Information

Date & Time: 19, Oct, 2024 14:12

Make	Toyota	Model	Vios
YOM	2024	Mileage	9,344
Registration No.	DBM5026	Chassis No.	PA1B18F31R4245583
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.0	146	123	127
2	Boot Lid	122.0	107	111	148
3	Roof	130.2	140	117	117/147
4	Left Front Fender	112.0	111	109	116
5	Left Front Door	112.0	112	111	113
6	Center Panel Left				
7	Left Rear Door	119.0	119	124	114
8	Left Back Panel	123.0	127	126	116
9	Right Front Fender	118.0	112	118	124
10	Right Front Door	122.0	124	121	121
11	Center Panel Right				
12	Right Rear Door	135.3	126	131	149
13	Right Back Panel	125.6	128	123	126

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes	Remarks Rear End Panel - Repair Traces - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : B	Functional Evaluation : B
Remarks Rear Side Member & Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Battery - Weak - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
tail lights are broken/ trunk cannot be opened/ aftermarket floor mats/ bumper needs to be replaced/ rear parking sensor damage