

General Information

Date & Time: 29, Oct, 2024 09:03

Make	Toyota	Model	Vios
YOM	2023	Mileage	28,174
Registration No.	DBG9971	Chassis No.	PA1B18F30P4204892
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	113	116	128
2	Boot Lid	124.3	117	129	127
3	Roof	112.0	122	105	110/111
4	Left Front Fender	113.6	113	109	119
5	Left Front Door	116.6	119	118	113
6	Center Panel Left				
7	Left Rear Door	116.0	121	116	111
8	Left Back Panel	123.0	131	121	117
9	Right Front Fender	105.6	104	104	109
10	Right Front Door	101.6	100	100	105
11	Center Panel Right				
12	Right Rear Door	111.6	117	108	110
13	Right Back Panel	114.3	114	110	119

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Rear Bumper, Lamps, Panels - Dent - Small / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no reverse camera/hairline around the vehicle//after market floor mats