


General Information

Date & Time: 13, Nov, 2024 11:00

Make	Toyota	Model	Vios
YOM	2024	Mileage	7,313
Registration No.	BAG3466	Chassis No.	PA1B18F35R4256781
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	127	117	133
2	Boot Lid	131.0	126	132	135
3	Roof	125.7	133	118	126/126
4	Left Front Fender	128.3	119	147	119
5	Left Front Door	126.0	123	131	124
6	Center Panel Left				
7	Left Rear Door	125.0	130	127	118
8	Left Back Panel	131.3	141	128	125
9	Right Front Fender	129.3	125	132	131
10	Right Front Door	123.0	122	122	125
11	Center Panel Right				
12	Right Rear Door	123.6	120	124	127
13	Right Back Panel	126.3	117	124	138

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

swirlmarks and hairline scratches around the exterior. with warranty booklet and user manual. trunk floor mat missing.