

General Information

Date & Time: 18, Nov, 2024 08:43

Make	Toyota	Model	Vios
YOM	2023	Mileage	18,954
Registration No.	EAG5687	Chassis No.	PA1B18F39P4219617
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	156.3	149	159	161
2	Boot Lid	130.3	131	133	127
3	Roof	114.7	117	112	111/119
4	Left Front Fender	236.6	250	237	223
5	Left Front Door	105.3	108	104	104
6	Center Panel Left				
7	Left Rear Door	108.3	111	109	105
8	Left Back Panel	115.3	122	115	109
9	Right Front Fender	114.3	113	111	119
10	Right Front Door	117.6	121	117	115
11	Center Panel Right				
12	Right Rear Door	121.3	118	118	128
13	Right Back Panel	109.6	107	108	114

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Medium	Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
hairline scratches around the exterior. With warranty booklet, user manual and tools.