Grading Report

General Information

Date & Time: 25, Nov, 2024 10:06

Make	Toyota	**Model**	Vios
YOM	2023	**Mileage**	30,007
Registration No.	NHJ1747	**Chassis No.**	PA1B18F38P4215701
CC	1.3	**Transmission**	CVT
Fuel Type	Gas	**Type of Body**	Sedan
Colour	Silver		

Body / Panel Condition

#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	**110.3**	111	106	114
2	Boot Lid	**112.0**	110	114	112
3	Roof	**100.8**	103	108	98/95
4	Left Front Fender	**102.3**	102	101	104
5	Left Front Door	**104.3**	105	104	104
6	Center Panel Left				
7	Left Rear Door	**104.0**	107	100	105
8	Left Back Panel	**109.3**	117	106	105
9	Right Front Fender	**100.4**	98	100	103
10	Right Front Door	**99.3**	105	100	93
11	Center Panel Right				
12	Right Rear Door	**106.3**	102	104	113
13	Right Back Panel	**109.0**	108	108	111

Overall Evaluation : B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

BLUE-T VEHICLE GRADING SYSTEM

Grading Report

Interior Evaluation : B

a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain

Remarks

(L) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Worn - Yes / Rear Seat - Grime - Medium / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes

Exterior Evaluation : C

A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap

Remarks

Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Dent - Small / Roof - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium

Frame Evaluation : A

Remarks

Defects not found

Functional Evaluation : B

Remarks

Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with tools and jack/ without warranty booklet/ no reverse camera/