

General Information

Date & Time: 16, Dec, 2024 17:56

Make	Toyota	Model	Vios
YOM	2023	Mileage	52,561
Registration No.	NII7597	Chassis No.	PA1B18F39P4203434
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.7	107	95	109
2	Boot Lid	99.2	100	96	102
3	Roof	88.4	97	78	85/95
4	Left Front Fender	86.7	84	84	92
5	Left Front Door	96.8	99	99	93
6	Center Panel Left				
7	Left Rear Door	90.4	92	90	89
8	Left Back Panel	95.8	100	95	92
9	Right Front Fender	92.0	96	87	93
10	Right Front Door	91.7	90	93	92
11	Center Panel Right				
12	Right Rear Door	90.6	92	91	89
13	Right Back Panel	87.6	88	88	88

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Worked - Small / Overall Interior - Worn as per age - Yes	Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch & Dent - Medium / (R) Front Fender, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / Roof - Dent - Small / (L) Front Door, Molding - Scratch - Medium
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
broken headlight/ hood cannot be closed/ gap on the front bumper/ with tools and spare tire and jack/ no warranty booklet