

General Information

Date & Time: 13, Jan, 2025 10:21

Make	Toyota	Model	Vios
YOM	2023	Mileage	43,176
Registration No.	DBI1142	Chassis No.	PA1B18F33P4215210
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.7	101	93	111
2	Boot Lid	268.9	97	115	595
3	Roof	93.4	101	85	91/96
4	Left Front Fender	88.5	91	90	85
5	Left Front Door	92.7	90	91	97
6	Center Panel Left				
7	Left Rear Door	96.0	100	96	92
8	Left Back Panel	103.6	105	106	100
9	Right Front Fender	85.8	87	86	85
10	Right Front Door	109.6	129	96	104
11	Center Panel Right				
12	Right Rear Door	109.1	89	94	144
13	Right Back Panel	94.2	95	92	96

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small / Ceiling - Grime - Small	Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Dent - Small / Trunk Hood, Rear Gate - Dent - Small / (L) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet and tools. driver side matting is not the original Vios Matting instead it's the innova matting.