

General Information

Date & Time: 23, Jan, 2025 18:30

Make	Toyota	Model	Vios
YOM	2024	Mileage	39,059
Registration No.	NHR2572	Chassis No.	PA1B18F34P4227043
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.3	100	99	102
2	Boot Lid	103.6	99	107	105
3	Roof	101.4	105	99	99/103
4	Left Front Fender	94.7	101	91	92
5	Left Front Door	93.7	91	88	102
6	Center Panel Left				
7	Left Rear Door	100.8	108	98	97
8	Left Back Panel	109.0	116	103	108
9	Right Front Fender	95.3	98	90	99
10	Right Front Door	92.6	90	89	99
11	Center Panel Right				
12	Right Rear Door	97.5	98	98	96
13	Right Back Panel	101.4	100	93	111

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Cut, Crack - Medium	Remarks Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Roof - Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

no spare tire/ no tools/ no warranty booklet/ with LTO plate/ cut on driver side tint