

General Information

Date & Time: 02, Feb, 2025 08:57

Make	Toyota	Model	Vios
YOM	2021	Mileage	39,818
Registration No.	DAV1015	Chassis No.	PA1B18F35M4143454
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.0	119	106	114
2	Boot Lid	105.6	103	102	112
3	Roof	104.4	110	104	97/107
4	Left Front Fender	94.0	95	90	98
5	Left Front Door	119.7	154	106	99
6	Center Panel Left				
7	Left Rear Door	117.9	162	97	95
8	Left Back Panel	110.3	117	111	103
9	Right Front Fender	95.7	96	95	96
10	Right Front Door	125.6	162	108	107
11	Center Panel Right				
12	Right Rear Door	105.8	98	104	116
13	Right Back Panel	110.0	103	109	118

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / (L) Front Floor Mat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Dent - Small / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Head Light, High Beam - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate number/spare tire/jack/warranty booklet/incomplete tools/No reverse camera/ no park light/ low beam issue/