

General Information

Date & Time: 05, Feb, 2025 13:54

Make	Toyota	Model	Vios
YOM	2023	Mileage	29,818
Registration No.	NIN6304	Chassis No.	PA1B18F38P4211847
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	121	108	117
2	Boot Lid	108.6	102	106	118
3	Roof	98.5	101	101	91/101
4	Left Front Fender	96.3	99	93	97
5	Left Front Door	99.1	100	98	99
6	Center Panel Left				
7	Left Rear Door	96.6	99	97	93
8	Left Back Panel	106.3	116	100	103
9	Right Front Fender	96.6	95	98	97
10	Right Front Door	104.0	106	105	101
11	Center Panel Right				
12	Right Rear Door	108.0	100	114	110
13	Right Back Panel	102.2	96	101	110

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Large / Ceiling - Grime - Small / (L) Front Trim - Grime - Minimal	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet, with spare tire, with jack and incomplete tools, with LTO plate, scratch/stone chip on front windshield, crack/gap front and rear bumper, front left tire worn