


General Information

Date & Time: 19, Feb, 2025 16:41

Make	Toyota	Model	Vios
YOM	2024	Mileage	18,974
Registration No.	NKD7214	Chassis No.	PA1B18F38R4258864
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	115	105	106
2	Boot Lid	100.1	101	93	106
3	Roof	103.1	104	104	94/111
4	Left Front Fender	92.5	98	85	96
5	Left Front Door	88.5	88	87	92
6	Center Panel Left				
7	Left Rear Door	99.2	105	100	93
8	Left Back Panel	105.3	118	105	93
9	Right Front Fender	98.0	96	100	98
10	Right Front Door	95.6	101	94	92
11	Center Panel Right				
12	Right Rear Door	103.9	97	104	111
13	Right Back Panel	105.3	102	103	111

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Large / Rear Seat - Grime - Small / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Trim - Grime - Small / Ceiling - Grime - Minimal	Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
no warranty booklet, no jack, no tools, no spare tire, with LTO plate, crack on right tail light