

General Information

Date & Time: 25, Feb, 2025 10:11

Make	Toyota	Model	Wigo
YOM	2020	Mileage	28,563
Registration No.	DBA9849	Chassis No.	MHKA4DF5FLJ044117
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.6	75	89	78
2	Boot Lid	83.1	82	84	83
3	Roof	64.2	59	75	63/60
4	Left Front Fender	75.2	76	76	74
5	Left Front Door	72.9	70	73	76
6	Center Panel Left				
7	Left Rear Door	76.4	83	74	73
8	Left Back Panel	73.8	78	77	67
9	Right Front Fender	80.7	82	83	77
10	Right Front Door	83.1	84	85	80
11	Center Panel Right				
12	Right Rear Door	81.8	88	79	79
13	Right Back Panel	81.9	79	78	89

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Repair mark - Difference in Color / (R) Front Fender, Molding - Repair mark - Difference in Color / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

no aranty booklet and tool/ no jack/ with spare tire and LTO plate