

General Information

Date & Time: 25, Feb, 2025 08:47

Make	Toyota	Model	Vios
YOM	2024	Mileage	16,341
Registration No.	CCC9164	Chassis No.	PA1B18F31R4256552
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.2	104	105	98
2	Boot Lid	95.3	91	96	100
3	Roof	97.1	100	96	94/99
4	Left Front Fender	95.1	101	94	90
5	Left Front Door	99.3	99	102	97
6	Center Panel Left				
7	Left Rear Door	96.1	100	97	91
8	Left Back Panel	111.0	124	107	102
9	Right Front Fender	97.5	102	96	95
10	Right Front Door	98.9	96	100	101
11	Center Panel Right				
12	Right Rear Door	100.6	98	100	104
13	Right Back Panel	99.5	100	94	105

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C		Exterior Evaluation : C	
			
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Worked - Large		Remarks Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Crack, Gap - Small	
Frame Evaluation : B		Functional Evaluation : A	
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes		Remarks Spare Key - Issue - Unexist	

Inspector Notes

with sparetire and tools/ with warranty booklet and LTO plate/ with jack
--