

General Information

Date & Time: 25, Feb, 2025 13:56

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,812
Registration No.	NIU8688	Chassis No.	PA1B18F37R4240310
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.7	109	99	112
2	Boot Lid	103.0	101	100	108
3	Roof	96.9	100	98	94/96
4	Left Front Fender	90.6	94	89	89
5	Left Front Door	100.3	97	101	103
6	Center Panel Left				
7	Left Rear Door	101.0	105	101	97
8	Left Back Panel	102.3	105	100	102
9	Right Front Fender	92.6	93	92	93
10	Right Front Door	97.0	97	99	95
11	Center Panel Right				
12	Right Rear Door	90.5	87	89	96
13	Right Back Panel	100.1	96	100	105

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal	Remarks (R) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet and jack. without spare tire and tools. with LTO plate. small gap at the right front bumper.