

General Information

Date & Time: 01, Mar, 2025 15:11

Make	Toyota	Model	Vios
YOM	2021	Mileage	40,178
Registration No.	NET4677	Chassis No.	PA1B18F35M4146810
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	105	109	108
2	Boot Lid	104.1	107	99	106
3	Roof	95.1	105	88	93/94
4	Left Front Fender	95.5	94	93	100
5	Left Front Door	102.3	100	101	106
6	Center Panel Left				
7	Left Rear Door	98.8	105	95	96
8	Left Back Panel	108.0	107	109	108
9	Right Front Fender	95.3	99	89	99
10	Right Front Door	93.9	90	94	98
11	Center Panel Right				
12	Right Rear Door	95.4	99	89	98
13	Right Back Panel	102.6	100	104	104

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Missing - Yes	Remarks Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack /with warranty booklet/No tools and No reverse camera